

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2018

Submitted Date:

11/02/2018

Document Number:

681701117

FIELD INSPECTION FORM

Loc ID 324288 Inspector Name: Arauza, Steven On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	
, Laramie		cogccnotifications@laramie-energy.com	All Inspections
Bankert, Wayne		wbankert@laramie-energy.com	
Chris, Clark		cclark@Laramie-Energy.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Spencer, Stan		stan.spencer@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414402	PIT	AC	11/17/2009		-	POND G	AC
437578	CENTRALIZED EP WASTE MGMT FAC	AC	06/13/2014		-	POND G G	EI

General Comment:

[COGCC Environmental inspection of Pond G pit facility. Follow-up to Field Inspection Report #681701069.](#)

[On inspection date, contractors were on location installing insulation around tanks in battery located NE of pit, precluding inspection of the tank battery. Unused HDPE flowline material referenced in previous Field Inspection Report has been removed by operator.](#)

Inspected Facilities

Facility ID: 414402 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 437578 Type: CENTRALIZE API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: 414402 Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: HDPE Liner Condition: Adequate

Comment: Liner has been repaired by operator in response to previous Field Inspection Report (doc #681701069). Note: Tears in liner were observed along anchor trench in two areas. See photos.

Corrective Action: Contact COGCC EPS Steven Arauza to discuss liner repair and tears in liner along anchor trench.

Date: 11/09/2018

Fencing:

Fencing Type: Livestock Fencing Condition: Inadequate

Comment: Operator has repositioned inlet hoses to prevent direct contact between metal fittings and pit liner in response to previous Field Inspection Report (doc #681701069). Position of sandbag beneath hose with hammer union is an improvement over previous conditions but insufficient to prevent contact due to potential hose movement. Single ratchet strap spanning width of pit was submerged in pit fluids on inspection date. See photos.

Corrective Action: Elevate hose with hammer union to prevent direct contact with pit liner. Repair or replace ratchet strap to prevent contact with pit fluids.

Date: 12/02/2018

Netting:

Netting Type: Mesh Netting Condition:

Comment: Wildlife mesh had been removed from pit and was stored along west side of pit on inspection date. Operator indicated via phone that the net is removed during the winter months to prevent damage from snow per an agreement between the operator and CPW. Two holes observed in NW corner of pit fence. See photos.

Corrective Action: Submit a Form 4 Sundry notice to provide documentation of netting agreement with CPW. Repair holes in pit fence to prevent access, per Rule 902.d.

Date: 11/09/2018

Anchor Trench Present: YES Oil Accumulation: YES 2+ feet Freeboard: YES

Comment: Oil observed in NE corner of pit. Contacted operator via phone on 11/1/2018 to notify and instructed them to remove oil from pit.

Corrective Action: Remove oil from pit per Rule 902.c. within 24 hours of COGCC notification.

Date: 11/02/2018

Permit:	Facility ID	Permit Num	Expiration Date
	414402	1630651	
	414402	1630651	
	291975	1433711	
	423514	2214297	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681701118	20181101 Field Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4630949