

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2018

Submitted Date:

10/30/2018

Document Number:

679701562

FIELD INSPECTION FORM

Loc ID 314687 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 12930
Name of Operator: CALCO DBA CALLISTER CO
Address: 1230 W 1400 N
City: LEHI State: UT Zip: 84043

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	
Callister, Jan	801-487-4721	Jec@apexoilventures.com	
Waldron, Emily		emily.waldron@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229263	WELL	SI	01/15/2014	GW	103-06358	CALLISTER-GOVERNMENT 4	PR

General Comment:

[follow up inspection to document 675102393](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	801-571-5890 and 970-620-2257		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	#		
Comment:	2 uncapped risers near well head. Not determined where the risers go.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 11/30/2018

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 229263 Type: WELL API Number: 103-06358 Status: SI Insp. Status: PR

Producing Well

Comment: Last recorded production is September 2013. No MIT recorded.
 Well is flowing audible gas to a building located 750' to the north. Flowline was traced from the building an additional 300' and runs to the west. No indication of gas leaks along 1050' path followed. (see attached photos)
 NOAV is in progress.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401817629	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4627043
679701563	inspection 679701562 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4627033