

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/29/2018

Submitted Date:

10/30/2018

Document Number:

689302224**FIELD INSPECTION FORM**

Loc ID 323891 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211109	WELL	PR	04/10/1997	GW	045-06868	DALEY 1	PR

General Comment:[Routine Field Inspection.](#)

Location					
Lease Road:					
Type	Main				
comment:					
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:	1-800-921-8252				
Corrective Action:					Date:
Good Housekeeping:					
Type	DEBRIS				
Comment:	Debris on location				
Corrective Action:	Comply with Rule 603.f .				Date: 11/29/2018
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	OTHER				
Comment:	Meter run, panel gates				
Corrective Action:					Date:
Type	OTHER				
Comment:	Pig stations, pipe fence				
Corrective Action:					Date:
Type	SEPARATOR				
Comment:	Panel gates				
Corrective Action:					Date:
Type	TANK BATTERY				
Comment:	5 strand barbed wire				
Corrective Action:					Date:
Equipment:					
Type: Deadman # & Marked	# 1				corrective date
Comment:	Unmarked deadman near battery fence on East corner				
Corrective Action:	Mark as required				Date: 11/29/2018
Type: Pig Station	# 7				
Comment:					
Corrective Action:					Date:

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	500 gallon methanol units at pig stations. These units are in there own metal water tank containment.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		,	
Comment:	Blow down tank at wellhead for bradenhead					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Comment:		
Corrective Action:		Date:
Venting:		
Yes/No	YES	
Comment:	Bradenhead open to vent, plumbed into tank.	
Corrective Action:		Date:
Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211109	Type:	WELL	API Number:	045-06868	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding						
Berms						
		Compaction				
		Gravel				
		Culverts				
Ditches						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401815391	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4625484
689302225	Inspection photo 689302225	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4625482