

Inspection Photos

API: 05-055-06309

Operator: ALTA MESA SERVICES LP

Inspection Date: 10/19/2018

Inspection Photos



Photo 1. Facing north along the access road to the location.

Inspection Photos



Photo 2. Facing north along the access road toward the location.

Inspection Photos



Photo 3. Facing northwest toward the location. The eastern portion of the location was not reclaimed.

Inspection Photos



Photo 4. Northeast side of the location facing south. The eastern portion of the location has not been reclaimed.

Inspection Photos



Photo 5. Facing southwest toward the location.

Inspection Photos



Photo 6. South side of the location facing northeast.

Inspection Photos



Photo 7. South side of the location facing northeast.

Inspection Photos



Photo 8. West side of the location facing north. The western portion of the location has been reclaimed.

Inspection Photos



Photo 9. West side of the location facing east.

Inspection Photos



Photo 10. Southwest of the location where unpermitted disturbance occurred. Facing north.

Inspection Photos



Photo 11. Southwest of the location where unpermitted disturbance occurred. Facing northwest.