

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2018

Submitted Date:

11/05/2018

Document Number:

690100881

FIELD INSPECTION FORM

Loc ID 318928 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 39560
Name of Operator: TOP OPERATING COMPANY
Address: 3609 S WADSWORTH BLVD STE 340
City: LAKEWOOD State: CO Zip: 80235

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Herring, Paul	303-727-9915	paul.herring@topoperating.com	
HERRING, MURRAY J	(303) 727-9915 x203	murray.herring@topoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426982	TANK BATTERY	AC	12/19/2011		-	Serafini GU #1 426982	EG
455244	OFF-LOCATION FLOWLINE	AC	05/30/2018		-	Wellhead Line 18NENE	EG

General Comment:

This inspection is pursuant to Order No. 1V-679 Engineering Integrity Inspection; Flowline pressure testing (off location and crude oil dump flowlines) witnessed by COGCC staff. Photos uploaded.

Inspected Facilities

Facility ID: 426982 Type: TANK API Number: - Status: AC Insp. Status: EG

Flowline

#1	Type: Dump Line	2 of Lines	
----	-----------------	------------	--

Flowline Description

Flowline Type: <u>Dump Line</u>	Size: <u>2"</u>	Material: <u>Carbon Steel</u>
Variance: <u>No</u>	Age: <u>10-15 Yrs</u>	Contents: <u>Crude Oil</u>

Integrity Summary

Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: No

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: COGCC Eng Integrity Inspector met with Top Operating personnel (Jeff Freitas) and witnessed off location and crude oil dump flowline pressure testing. The City of Longmont 1, Sherwood 1 and Sherwood 2 flowlines were pressure tested for approx 30 Minutes; the results of pressure testing for all (3) flowlines are deemed satisfactory (see individual well inspection reports). The (2) crude oil dump flowlines (at the Serafini facility/ battery) servicing all three wells were also pressure tested. The tests recorded minimal pressure deviations (loss < 10%) and adequate stabilization and are deemed passing/ satisfactory per COGCC rule 1104. Top personnel recorded the data on a pressure testing form (document is uploaded to FIR).

Corrective Action: _____ Date: _____

Facility ID: 455244 Type: OFF- API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
Note: Top Operating personnel conducted pressure testing of the produced water dump flowlines. These (2) pressure tests were not witnessed by COGCC staff. The operator shall submit the data for these pressure tests to COGCC Eng Integrity staff for review.	maclarej	11/05/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100894	Flowline pressure testing form	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4636004
690100895	Signage at tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4636005
690100896	Tank battery (view to east)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4636006
690100897	FL Pressure test in progress (oil dump flowline)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4636007