

Inspection Photos

Location Name: 05-103-08920 (TAIGA MOUNTAIN 6-22)

Location ID: 315653

Inspection: 679701662



Location photo looking east



Tank battery



Inspection Photos

Location Name: 05-103-08920 (TAIGA MOUNTAIN 6-22)

Location ID: 315653

Inspection: 679701620



Well head



Battery sign



Inspection Photos

Location Name: 05-103-08920 (TAIGA MOUNTAIN 6-22)

Location ID: 315653

Inspection: 679701620



Tank missing NFPA label and current phone number



Tank missing NFPA label and current phone number



Inspection Photos

Location Name: 05-103-08920 (TAIGA MOUNTAIN 6-22)

Location ID: 315653

Inspection: 679701620



Separator had prior leak



Condensate leaking from tank photo 1

Inspection Photos

Location Name: 05-103-08920 (TAIGA MOUNTAIN 6-22)

Location ID: 315653

Inspection: 679701662



Condensate leaking from tank photo 2



Condensate leaking from tank photo 3

