

**Inspection Photo
EM 30-2
API # 045-09267
Inspection # 689302295**



Location Photo #1



Location Photo #2, tank float rod in battery containment.

**Inspection Photo
EM 30-2
API # 045-09267
Inspection # 689302295**



Location Photo #3, Oily stained rock in battery containment.



Location Photo #4, Oily stained rock in battery containment.

**Inspection Photo
EM 30-2
API # 045-09267
Inspection # 689302295**



Location Photo #5, Oily stained rock in battery containment. Tank maintenance.



Location Photo #6, Oily stained rock in battery containment.