

**Inspection Photo**  
**Cruz 29-12C**  
**API # 045-11628**  
**Inspection # 689302301**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo  
Cruz 29-12C  
API # 045-11628  
Inspection # 689302301**



**Location Photo #3, unused equipment in battery.**



**Location Photo #4, unused equipment in tank battery.**

**Inspection Photo  
Cruz 29-12C  
API # 045-11628  
Inspection # 689302301**



**Location Photo #5, unmarked flow line riser.**



**Location Photo #6, Mechanical condition of gauge hatches.**

**Inspection Photo**  
**Cruz 29-12C**  
**API # 045-11628**  
**Inspection # 689302301**



**Location Photo #7, Mechanical condition of tank.**



**Location Photo #8, Oily stained rock in battery containment area.**

**Inspection Photo**  
**Cruz 29-12C**  
**API # 045-11628**  
**Inspection # 689302301**



**Location Photo #9, Oily stained rock in battery containment area.**



**Location Photo #10, Oily stained rock in battery containment area.**

**Inspection Photo**  
**Cruz 29-12C**  
**API # 045-11628**  
**Inspection # 689302301**



**Location Photo #11, Oily stained rock in battery containment area.**



**Location Photo #12, Oily stained rock in battery containment area.**