

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2018

Submitted Date:

11/07/2018

Document Number:

680404004**FIELD INSPECTION FORM**
 Loc ID 417723 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10493Name of Operator: ALANCO ENERGY SERVICES INCAddress: 7950 E ACOMA DRIVE STE 111City: SCOTTDALE State: AZ Zip: 85260**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Koehler, Bob		bob.koehler@state.co.us	
,		dnr_cogccengineering@state.co.us	
Carlson, John	(480) 505-4869	john@alanco.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417724	WELL	PR		LO	077-10096	Deer Creek SWD 1	TA

General Comment:

Followup inspection for Doc#680401106 (1/12/2017).
 Alanco Energy Services Inc. (Oper# 10493) contact info is no longer in service.
 Deer Creek Solid Waste Facility site is permitted under CDPHE.
 Well is not being used and has no useful purpose or approved plan and should be plugged per Rule 208

Location			
Lease Road:			
Type	Main		
comment:			
Corrective Action	L	Date:	
Type	Access		
comment:	Private road with locked gate. Goodwin Services Inc Disposal Site 970-243-2783.		
Corrective Action	L	Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted. No sign on wellhead. Photo attached		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	04/07/2017
Emergency Contact Number:			
Comment:	No Emergency Contact Number.		
Corrective Action:	Install sign to comply with Rule 210.	Date:	02/24/2017
Good Housekeeping:			
Type	WEEDS		
Comment:	Trash and debris around wellhead.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/27/2017
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	T-post but no fencing around wellhead. Metal grate over 4' corrugated cellar.		
Corrective Action:		Date:	
Equipment:			
Type: Other	# 0		corrective date
Comment:	No production/injection equipment is located onsite. All tanks/pits/equipment are related to CDPHE permitted water disposal site. 3-400 bbl produced water tanks with cement bermed offload station. Tanks are empty and access hatches are removed. Filter pods disconnected. 1-500 bbl and 2-400 bbl skim tanks as pre-filter operations for waste water disposal facility. Tanks are empty and access hatches are removed. Filter pods disconnected. Metal berms and liners removed. 4-media filter pods disconnected. 1-vertical Ecodyne Hydroflow inside housing, 1-100 bbl tank, 2-generators, various pumps and flow lines to (2) 3.5 acre HDPE lined evap pits. Office trailer. Tanks and filtration equipment in process of removal.		

Inspected FacilitiesFacility ID: 417724 Type: WELL API Number: 077-10096 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Well Located on Deer Creek Solid Waste Facility (CDPHE).
COGCC UIC Class 2 disposal well permit application denied 6/26/2011 (Doc#2617226).
EPA UIC Class 1 disposal well permit application denied 2/19/2014 (Doc#2089861).
Last MIT 10/30/2013. No current MIT on record or delinquent as required by Rule 326.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Well is listed as PR on COGIS scout card. This well was drilled in 2011 with intent to use as disposal well. No UIC permit was issued. Well was perforated to test water sample. Perfs were covered with fine mesh sand and 2 sks cement set in order to perform SI/TA MIT in 2013. No CA completed from previous inspection doc#680401106 on 1/12/2017.	browning	11/02/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680404006	Inspection photos 11/2/2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4637072