

**Inspection Photo**  
**Clough RMV 225-22**  
**API # 045-12248**  
**Inspection # 689302313**



**Location Photo #1**

