

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/07/2018

Submitted Date:

11/07/2018

Document Number:

689302315

FIELD INSPECTION FORM

Loc ID 335069 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262717	WELL	PR	07/12/2002	GW	045-08049	CLOUGH RMV 160-22	PR
284637	WELL	PR	05/09/2006	GW	045-12248	CLOUGH RMV 225-22	PR
284639	WELL	PR	05/09/2006	GW	045-12247	CLOUGH RWF 423-22	PR

General Comment:

[Routine Field Inspection.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Emergency Contact Number:	
Comment:	1-970-285-9377
Corrective Action:	
	Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panel fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 262717 Type: WELL API Number: 045-08049 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 284637 Type: WELL API Number: 045-12248 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 284639 Type: WELL API Number: 045-12247 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Slope Roughening						
		Compaction				
Seeding						
		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302316	Inspection photo 689302316	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4637893