

Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200




Photo #1

Federal Goshawk 28-13 (API # 05-123-22634) wellhead

Sign is illegible

Bradenhead NOT plumbed to surface

From previous FIR



Photo #2

Federal Goshawk 28-13 wellhead

Sign is Legible

Bradenhead is plumbed to surface



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200



Photo #3

**Federal Goshawk 28-13, Fed Plover 28-5X,
Fed Toucan 28-14
Battery**



Photo #4

**Federal Goshawk 28-13, Fed Plover 28-5X,
Fed Toucan 28-14
Behind Tank Battery
Depression | Unpermitted pit**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200



Photo #5

Federal Goshawk 28-13, Fed Plover 28-5X,

Fed Toucan 28-14

Battery Sign is illegible

From previous FIR



Photo #6

Federal Goshawk 28-13, Fed Plover 28-5X,

Fed Toucan 28-14

Battery Contact info is Legible



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200



Photo #7

Federal Goshawk 28-13, Fed Plover 28-5X,

Fed Toucan 28-14

Crude oil tanks poor paint & rust

From previous FIR



Photo #8

Federal Goshawk 28-13, Fed Plover 28-5X,

Fed Toucan 28-14

Crude oil tanks poor paint & rust



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200



Photo #9

Federal Goshawk 28-13 Access road

Road needs repaired

From previous FIR



Photo #10

Federal Goshawk 28-13 Access road

Road has been graded



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200



Photo #11

**Federal Goshawk 28-13, Fed Plover 28-5X,
Fed Toucan 28-14**

Weeds on pit bank – from prev. FIR



Photo #12

**Federal Goshawk 28-13, Fed Plover 28-5X,
Fed Toucan 28-14**

Weeds on pit bank - cleared



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200



Photo #13

**Federal Goshawk 28-13, Fed Plover 28-5X,
Fed Toucan 28-14**

Gaps or holes in Pit netting



Photo #14

**Federal Goshawk 28-13, Fed Plover 28-5X,
Fed Toucan 28-14**

Unpermitted pit – SE corner



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Goshawk - 68N60W / 28SWSW

Location #: 305200



Photo #15

Federal Goshawk 28-13, Fed Plover 28-5X,

Fed Toucan 28-14

Sheen on pit – 3 inch



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources