

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2018

Submitted Date:

11/07/2018

Document Number:

689801868

**FIELD INSPECTION FORM**

Loc ID 312902 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 95960  
Name of Operator: WEXPRO COMPANY  
Address: P O BOX 45003  
City: SALT LAKE CITY State: UT Zip: 84145-

**Findings:**

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone        | Email                         | Comment |
|--------------------|--------------|-------------------------------|---------|
| Fredrickson, Tammy | 307-352-7566 | Tammy.Fredrickson@questar.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 222798      | WELL | SI     | 07/01/2018  | GW         | 081-06158 | DONNELL-GOVERNMENT 15 | SI          |

**General Comment:**

[Routine FIU inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | BATTERY   |       |            |
| Comment:           |   |       |            |
| Corrective Action: |   | Date: |            |
| Type               | WELLHEAD  |       |            |
| Comment:           |   |       |            |
| Corrective Action: |   | Date: |            |
| Type               | CONTAINERS  |       |            |
| Comment:           | 500 gallon methanol   |       |            |
| Corrective Action: |   | Date: |            |
| Type               | TANK LABELS/PLACARDS  |       |            |
| Comment:           | Produced water NFPA diamond has flammability rating of "0".   |       |            |
| Corrective Action: | Comply with rule 210.d. Produced water flammability must accurately reflect the contents of the tank. To list a flammability of "0" please provide laboratory analysis to support "0" rating. | Date: | 01/07/2019 |

Emergency Contact Number:

Comment: 1-800-341-3129

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type: Deadman # & Marked        | #                    |       | corrective date |
|---------------------------------|----------------------|-------|-----------------|
|                                 | # 4                  |       |                 |
| Comment:                        |                      |       |                 |
| Corrective Action:              |                      | Date: |                 |
| Type: Gas Meter Run             | # 1                  |       |                 |
| Comment:                        | 40.92200, -108.74660 |       |                 |
| Corrective Action:              |                      | Date: |                 |
| Type: Horizontal Heater Treater | # 1                  |       |                 |
| Comment:                        | 40.92200, -108.74660 |       |                 |
| Corrective Action:              |                      | Date: |                 |
| Type: Bird Protectors           | #                    |       |                 |
| Comment:                        |                      |       |                 |
| Corrective Action:              |                      | Date: |                 |

**Tanks and Berms:**

| Contents       | # | Capacity | Type             | Tank ID | SE GPS                |
|----------------|---|----------|------------------|---------|-----------------------|
| PRODUCED WATER | 1 | 200 BBLs | HEATED STEEL AST |         | 40.922080,-108.746110 |

|                    |  |  |       |
|--------------------|--|--|-------|
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate |                     |                     | Adequate    |

|                    |  |  |       |
|--------------------|--|--|-------|
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    |       |
|                    |    | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  |       |
|                    |  | Date: |

**Inspected Facilities**

Facility ID: 222798 Type: WELL API Number: 081-06158 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Compaction              | Pass                  |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
| Ditches          | Pass            |                         |                       |               |                          |         |
| Compaction       | Pass            |                         |                       |               |                          |         |

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 689801905    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4638036">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4638036</a> |