

Final Reclamation Inspection

November 6, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-001-09223

Inspection Document #: 682404155

Adams County, CO

SWNW Section 5 T1S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HSR-DREYER #5-5
API: 05-001-09223



Photo 1. Photo taken from the northern location. Active Remediation (#4891) is still underway. Operator shall control weeds and erosion until the Location meets Rule 1004 standards, including during active remediation. Active midstream gathering equipment is located east, adjacent to this location- see Photo 3. Photo illustrates a monitoring well location.

Inspection Photos
Location Name: HSR-DREYER #5-5
API: 05-001-09223



Photo 2. Reference photo taken north of location, facing Northwest.

Inspection Photos
Location Name: HSR-DREYER #5-5
API: 05-001-09223



Photo 3. Photo taken from the approximate center of location, facing East. See comments under Photo 1.