

Inspection Photos

Operator: BP Production

API: 05-067-06667

Date: 10/24/2018



Photo 1. View of the project area from the northwestern corner facing center. Well pad is not recontoured. Farm equipment stored on the well pad.



Photo 2. View of the western project area from the northwestern corner facing southward.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of erosional channels in the northeastern project area where sediment flows off of the project area.



Photo 5. View of erosional channels up to 18 inches wide and deep within the northeastern project area.



Photo 6. View of rilling within the northern project area.



Photo 7. View of riser that remains within the project area.



Photo 8. View of dry hole marker, barrier fencing, and signage at the plugged well head.



Photo 9. View of another riser that remains within the project area.



Photo 10. View of musk thistles (*Cirsium arvense*) west of the project area. Approximately 100 observed.



Photo 11. View of Russian knapweeds (*Acroptilon repens*) within the southwestern project area. Approximately 200 individuals observed.