

Inspection Photo
Roles 13-14B
API # 045-10056
Inspection # 689302323



Location Photo #1



**Location Photo #2, secondary battery
containment repaired.**

Inspection Photo
Roles 13-14B
API # 045-10056
Inspection # 689302323



**Location Photo #3, Secondary battery
containment repaired.**