

Inspection Photos

11/8/2018

Operator: H & M PETROLEUM CORPORATION -
10032

Location ID: 458288

Inspection Doc. Number: 682504101

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: H & M PETROLEUM CORPORATION - 10032
Location ID: 458288



Photo 1: Photo taken from the west end of the location, facing north. No construction has begun on pad at time of the inspection. Photo shows vegetation of the location prior to disturbance activities.

Inspection Photos
Operator: H & M PETROLEUM CORPORATION - 10032
Location ID: 458288



Photo 2: Photo taken from the west end of the location, facing northeast. No construction has begun on pad at time of the inspection. Photo shows vegetation of the location prior to disturbance activities.



Photo 3: Photo taken from the west end of the location, facing east. No construction has begun on pad at time of the inspection. Photo shows vegetation of the location prior to disturbance activities.

Inspection Photos
Operator: H & M PETROLEUM CORPORATION - 10032
Location ID: 458288



Photo 4: Photo taken from the west end of the location, facing north. Photo shows locate flags for an underground power line for the wind farm. Operator indicated that no soil salvage will be conducted on the pad due to the line.



Photo 5: Photo taken from the location. Photo shows vegetation of the location prior to disturbance activities. Location appears to be in CRP. Vegetation observed appears to be predominantly Cheatgrass with patches of Smooth brome, Yellow Indian grass, Little Bluestem, Western Wheatgrass, Switchgrass, Blue Grama, Russian thistle, etc...



Photo 6: Photo taken from the southeast end of the location, facing west. No construction has begun on pad at time of the inspection. Photo shows vegetation of the location prior to disturbance activities.

Inspection Photos
Operator: H & M PETROLEUM CORPORATION - 10032
Location ID: 458288



Photo 7: Photo taken from the southeast end of the location, facing northwest. No construction has begun on pad at time of the inspection. Photo shows vegetation of the location prior to disturbance activities.

Inspection Photos
Operator: H & M PETROLEUM CORPORATION - 10032
Location ID: 458288



Photo 8: Photo taken from the north of the location. Photo shows a “wind blown” area where sediment deposition from the adjacent cropland has built up over time. Operator is taking soils from this area to build up the pad and a portion of the access road that passes over a pipeline.



Photo 9: Photo taken from the section oil and gas access road that turns from North/south to east/west. Photo shows a “wind blown” area where sediment deposition from the adjacent cropland has built up over time. Operator is taking soils from this area to build up the pad and a portion of the access road that passes over a pipeline.

Inspection Photos
Operator: H & M PETROLEUM CORPORATION - 10032
Location ID: 458288



Photo 10: Photo taken from the access road north of the location. Photo shows area of access road operator has built up due to a pipeline.