

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2018

Submitted Date:

11/06/2018

Document Number:

682504087

FIELD INSPECTION FORM

Loc ID 316908 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-----------------------|---------|
| | | rob.young@state.co.us | |
| | | gfritzler@bresnan.net | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 109570 | PIT | AC | | | - | DECKER "B" | RI |
| 109571 | PIT | AC | | | - | DECKER "B" | RI |
| 109572 | PIT | AC | | | - | DECKER "B" | RI |
| 117727 | PIT | AC | | | - | DECKER "B" 1 | RI |
| 233118 | WELL | PR | 07/01/2014 | OW | 121-05140 | DECKER B 1 | RI |

General Comment:

This is a follow-up inspection regarding a produced water discharge from the northeast corner of the pits. See inspection #682504077. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 109570 Type: PIT API Number: - Status: AC Insp. Status: RI

Facility ID: 109571 Type: PIT API Number: - Status: AC Insp. Status: RI

Facility ID: 109572 Type: PIT API Number: - Status: AC Insp. Status: RI

Facility ID: 117727 Type: PIT API Number: - Status: AC Insp. Status: RI

Facility ID: 233118 Type: WELL API Number: 121-05140 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

| Type: | Lined: | Pit ID: | Lat: | Long: |
|-------|--------|---------|------|-------|
|-------|--------|---------|------|-------|

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: 11/04/2018

Attached Documents

You can go to COGCC Images (<https://ogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401828702 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4635866 |
| 682504088 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4635848 |