

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2018

Submitted Date:

11/05/2018

Document Number:

689900323**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 429618 COSTA, RYAN 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10630Name of Operator: ALTA MESA SERVICES LPAddress: 15021 KATY FREEWAY SUITE 400City: HOUSTON State: TX Zip: 77094**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
JAMESON MAX		mjameson@altamesa.net	
KASSAB DIANE		dkassab@altamesa.net	

General Comment:

This is a Follow Up Inspection of the previous inspections document number 673504379, 673504439, 689900032, 689900273, 674902271, and NOAV number 40143515.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	The List B noxious weeds noticed in the previous inspection have been removed. It is likely that the noxious weeds will return during the following growing season. Ongoing weed control will need to be performed.		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	The unused pipe and equipment have been removed.		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Degraded hay bales have been removed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Fail Recontoured Fail 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____ I _____

Comment

Interim reclamation was not performed prior to plugging the well. A form 6 Well Abandonment Report was submitted indicating the well was plugged and abandoned on 12/2/2017. The total area of the location was 4.42 acres excluding the new unpermitted disturbance. The 2A specifies the size of the location after Interim Reclamation must be 1.2 acres. The operator was directed to request delayed interim reclamation following the NTO: Interim Reclamation Procedures for Delayed Operations. A complete delayed interim reclamation request was not submitted. The location has been out of compliance for Interim reclamation since 2014.

Corrective Action

Perform Interim reclamation and reduce the size of the location as specified in the 2A. The corrective action date is set for when Interim reclamation should have occurred, 3/25/2014.

Date **03/25/2014**Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged In Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded Fail Contoured Fail Culverts removed Fail

Gravel removed Fail

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured Fail

Compaction alleviation Fail Dust and erosion control _____

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present In Process Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:	It appears the well was plugged and abandoned on 12/2/2017. Final Reclamation was recently performed on the western portion of the location. The access road and eastern portion of the location have not been reclaimed. The location does not meet the 1004 reclamation requirements. Final Reclamation should have been performed in the first favorable growing season, Spring of 2018.		Date	
Corrective Action:	Reclaim the access road and eastern portion of the location. Remove the cattle guard and culvert from the access road.		Date	
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>	Multi-Well Location
			<input type="checkbox"/>	

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	In Process					
Mulching	In Process					

Comment:	The unpermitted disturbed area was reclaimed and vegetation appears to be establishing. It does not appear that additional BMP's were installed since the previous inspection however, vegetation appears to have stabilized the disturbance area.		Date:	
Corrective Action:			Date:	

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site the unpermitted disturbance area and the location.	CostaR	10/26/2018
The unpermitted disturbed area was reclaimed and vegetation appears to be establishing. The unpermitted area is outside of the fenced in location and appears to be heavily grazed by livestock.	CostaR	10/26/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401828276	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4635426
689900325	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4635422