

Inspection Photos

Loc#436801

Operator: Sandridge

Inspection Number: 692400342

Inspection Date: 10/30/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to North.

October 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#436676 Surprise Central Facility



Photo#2:
View of erosion on East Cut slope.

October 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#436676 Surprise Central Facility



Photo#3:
View of Fill slope at West side of site.

October 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#436676 Surprise Central Facility



Photo#4:

View of drainage area at Southwest corner of site where sediment is collecting & moving off site. Insert of damaged wattles that have become debris.

October 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#436676 Surprise Central Facility



Photo#5:

Interim Reclamation areas are sparse to bare of desirable vegetation, areas are weedy & hard-packed. Arrow indicates where sediment is migrating.

October 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#436676 Surprise Central Facility



Photo#6:
Cuttings storage area at Southeast corner of site, adjacent to entry.

October 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Loc#436676 Surprise Central Facility