

Construction and Stormwater Inspection

November 9, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 457013

Inspection Document #: 682404197

Weld County, CO

SWNW Section 21 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location ID: 457013
Location Name: REESE /22-21HZ



Photo 1. Photo taken from the entrance of location off CR20, facing North. Vehicle tracking devices have been installed and appear to be in proper functioning condition.



Photo 2. Photo taken from the eastern perimeter of the location, facing North. Photo illustrates a ditch and berm BMP.

Inspection Photos
Location ID: 457013
Location Name: REESE /22-21HZ



Photo 3. Photo taken from the northeastern location, facing West. Photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking.



Photo 4. Photo taken from northeastern location, facing West. See comments under Photos 2 & 3.

Inspection Photos
Location ID: 457013
Location Name: REESE /22-21HZ



Photo 5. Photo taken from the northwest location, facing South. See comments under Photo 2.



Photo 6. Photo taken from the western location, facing South. Fill slopes have been temporarily stabilized with equipment tracking. Location appears to be sandy and will likely need additional BMPs to control and manage for wind erosion.

Inspection Photos
Location ID: 457013
Location Name: REESE /22-21HZ



Photo 7. Photo taken from the southwest perimeter of the location, facing Southeast. Photo illustrates a sediment trap with a temporarily stabilized outlet.



Photo 8. Photo taken from the southern perimeter of the location, facing East. See comments under Photos 2 and 6.

Inspection Photos
Location ID: 457013
Location Name: REESE /22-21HZ



Photo 9. Photo taken from the southeast perimeter of the location, facing West. See comments under Photo 7. Sediment trap does not appear to be constructed in a logical location based off the topography of the well site.



Photo 10. Photo taken from the southeast perimeter of the location, facing North. See comments under Photo 2.