

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2018

Submitted Date:

11/14/2018

Document Number:

694400056**FIELD INSPECTION FORM**Loc ID 305921 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS
Ash, Margaret		margaret.ash@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Precup, Jim		james.precup@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283714	WELL	SI	11/01/2015	OW	123-23683	KREYKES 13-11	SI

General Comment:

Inspected FacilitiesFacility ID: 283714 Type: WELL API Number: 123-23683 Status: SI Insp. Status: SI**Workover**Comment:

Inspection in response to fire.
On 11/14/2018, Noble Energy rig management and a TEC work over rig crew moved onto the Kreykes 13-11 to begin plug and abandonment orders. Prior to moving onto the well, rig crews found the well to be pressurized, in an attempt to blow the well down to workable pressures, the rig crew began opening the wellbore to an open top "gas buster" lay down open top tank by way of choke manifold.
Shortly after flowing the well, a fire broke out in the open top tank, and spread to the neighboring work tank.
Windsor FD was utilized to extinguish the blaze, and released the scene immediately after the fire was out.
No injuries were reported at the time of inspection.
Grounding and bonding was observed on both work tanks (see photos).
Fire authority will determine causation, and Noble Energy will submit proper notification to the commission via form 22.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694400057	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4644250