

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/13/2018

Submitted Date:

11/14/2018

Document Number:

689801925**FIELD INSPECTION FORM**Loc ID 448834 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Inspections, General		sandridgeenvironmental@san dridgeenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448969	WELL	PR	08/16/2018		057-06593	Grizzly 0881 2-1H36	PR

General Comment:[Bradenhead test witness.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Misc parts strewn around pump jack base.		
Corrective Action:	Comply with Rule 603.f .	Date:	11/26/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Pump Jack	<= 1 bbl		
Comment:	5 gallon bucket at pumpjack with no containment, actively overflowing and dripping into pool of oil.			
Corrective Action:	Remove free fluids and contact COGCC EPS staff per Rule 906.b.			Date: 11/15/2018

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 448969 Type: WELL API Number: 057-06593 Status: PR Insp. Status: PR**BradenHead**

Comment: Inspector on location to witness bradenhead test. Drip of oily fluid was present from bradenhead valve for entire 30 minute test. SPL personel were unable to catch sample because there was not enough flow/volume.
Well was pumping during test. Tubing and production casing between 100 and 110 PSI for 30 minutes.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689801929	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4644438