

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2018

Submitted Date:

11/15/2018

Document Number:

689302348**FIELD INSPECTION FORM**

Loc ID 334622 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265893	WELL	TA	11/01/2017	GW	045-09086	ROSE RANCH 15-8 (D14)	TA

General Comment:

[10 day MIT notification recieved. Document #401818017. D&B water services on site to perform test.](#)

Inspected FacilitiesFacility ID: 265893 Type: WELL API Number: 045-09086 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Starting psi -411 Extended test 5 minutes for pressure stabilization.
5 min- psi- 409
10 min- psi- 409
15 min- psi-408
20 min- psi- 408
3-PSI loss

Starting BH psi- 4
Ending BH psi - 4

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302355	Inspection photo 689302355	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4645668