

Construction and Stormwater Inspection

November 14, 2018

Operator: PDC ENERGY INC - #69175

Location ID: 452785

Inspection Document #: 682404203

Weld County, CO

SESE Section 6 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Harold /4N64W6Y
Location ID: 452785



Photo 1. Photo taken from the southern perimeter of the location, facing East. Photo illustrates a ditch and berm BMP that has been installed around the entire perimeter of the location in conjunction with other BMPs.



Photo 2. Photo taken from the southern perimeter of the location, facing East. Photo illustrates the start of a perimeter BMP disturbance. BMP was moved more north. Operator will be responsible for recontouring the said disturbance and comply with other Rule 1004 standards (i.e., vegetation).

Inspection Photos
Location Name: Harold /4N64W6Y
Location ID: 452785



Photo 3. Photo taken from the southern perimeter of the location, facing Northeast. Photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking. Also, a retention area in conjunction with the ditch and berm BMP has been installed.



Photo 4. Photo taken from the southeastern perimeter of the location, facing North. See comments under Photo 1 & 3.

Inspection Photos
Location Name: Harold /4N64W6Y
Location ID: 452785



Photo 5. Photo taken from the eastern perimeter of the location, facing Southwest. Photo illustrates a sediment trap with a temporarily stabilized outlet. Also, photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking.



Photo 6. Photo taken from the northeastern perimeter of the location, facing North. See comments under Photo 5.

Inspection Photos
Location Name: Harold /4N64W6Y
Location ID: 452785



Photo 7. Photo taken from the northeastern perimeter of the location, facing West. Photo illustrates the ditch and berm BMP, and the temporarily stabilized topsoil stockpile.



Photo 8. Photo taken from the northern perimeter of the location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Harold /4N64W6Y
Location ID: 452785



Photo 9. Photo taken from the northern perimeter of the location, facing South. See comments under Photo 3. Also, photo illustrates pad areas stabilized with gravel.



Photo 10. Photo taken from the western perimeter of the location, facing South. See comments under Photo 1. Straw wattles have been installed in conjunction with the western ditch and berm BMP.