

Inspection Photos
Location Name: CHURCH 2
Location ID: 05-103-05331
Inspection: 679701727



Photo 1. Location looking south.



Photo 2. Weeds next to pump jack.

Inspection Photos
Location Name: CHURCH 2
Location ID: 05-103-05331
Inspection: 679701727



Photo 3. Insufficient berm capacity due to short berm on north side.



Photo 4. Trash on loading road below tank battery.

Inspection Photos
Location Name: CHURCH 2
Location ID: 05-103-05331
Inspection: 679701727



Photo 5. Tank battery looking north.