

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28NWNE

Location #: 323461



Photo #1

Sooner Unit 2-28 (API # 05-123-13065) wellsite

Bradenhead NOT plumbed to surface

from previous FIR



Photo #2

Sooner Unit 2-28 wellsite

Bradenhead NOT plumbed to surface

Tubing appears to have been pulled from well

Stained soil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28NWNE

Location #: 323461



Photo #3

Sooner Unit 2-28 wellsite

Sign not legible

Emergency number not legible

Unused equipment from previous FIR



Photo #4

Sooner Unit 2-28 wellsite

Sign not legible

Emergency number not legible

Unused equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28NWNE

Location #: 323461



Photo #5

Sooner Unit 2-28 Pump jack - gearbox

Stained soil

from previous FIR



Photo #6

Sooner Unit 2-28 Pump jack - gearbox

Stained soil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28NWNE

Location #: 323461



Photo #7

Sooner Unit 2-28 Pump jack
Unused equipment – belt guards
from previous FIR



Photo #8

Sooner Unit 2-28 Pump jack
Unused equipment – belt guards



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28NWNE

Location #: 323461



Photo #9

Sooner Unit 2-28 wellsite area

Tubing appears to have been pulled from well

Tubing on trailer



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28NWNE

Location #: 323461



Photo #10

Sooner Unit Battery

from previous FIR



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources