

**Inspection Photo
Schirer 13D-26
API # 045-14917
Inspection # 689302378**



Location Photo #1



Location Photo #2

**Inspection Photo
Schirer 13D-26
API # 045-14917
Inspection # 689302378**



Location Photo #3, Oily stained rock in battery containment.



Location Photo #4, Stained Material on West end of battery.