

**Inspection Photo  
Last Dance 34-10C  
API # 045-12985  
Inspection # 689302392**



**Location Photo #1**



**Location Photo #2**



**Inspection Photo  
Last Dance 34-10C  
API # 045-12985  
Inspection # 689302392**



**Location Photo #3**



**Location Photo #4, Holes in battery liner.**



**Inspection Photo  
Last Dance 34-10C  
API # 045-12985  
Inspection # 689302392**



**Location Photo #5, Holes in battery liner**



**Location Photo #6, Holes in battery liner.**