

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Excavated material staged on Thomas Jacquez E #1 location.



Soil excavated from pipeline ROW.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Spill/Release Point ID #458834 source.



Excavated 6" fiberglass produced water pipeline.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Downstream failure of fiberglass line.



Upstream failure of fiberglass line. Abandoned steel gathering line in left of photo.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Failure points located above sandbags.



Initial excavation of flow path.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Valve can upstream of release point.



Ponds #1-3.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Boom across High Flume Canyon siphon inlet.



Booms in place along Citizen's Animas Ditch.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Head gate to Pond #4.



Boom in Pond #4 near inlet.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Absorbent booms across siphon bypass and High Flume Canyon.



Photo along High Flume Canyon, downstream of last photo.