

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/22/2018

Submitted Date:

11/20/2018

Document Number:

688800341**FIELD INSPECTION FORM**Loc ID 306832 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Baca, Matthew		matthew.baca@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216383	WELL	PA	08/19/2003	GW	067-07989	STATE GAS COM "MZ" 1	EI
269119	WELL	PR	08/18/2003	GW	067-08858	STATE MZ 1R	EI
443350	WELL	PR	07/18/2016	LO	067-09955	Rhodes 1	EI

General Comment:

On October 22, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Rhodes #1. For the most recent field inspection report of this facility, please refer to document #685200556.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Label and placard on PBV.		
Corrective Action:			Date:
Type	OTHER		
Comment:	PA marker for State Gas Com MZ-1 (API #067-07989).		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing signs near location entrance.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Workover rig recently moved off of Rhodes #1. A Weatherford air package, an M&R tubing trailer, portable toilet, and a horizontal tank were on location at the time of this inspection.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	WELLHEAD		
Comment:	Wellhead, pump jack, and surrounding gravel are stained and wet.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 12/20/2018
Other	Pump Jack		
Comment:	Stained gravel near exhaust for pump jack.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 12/20/2018
In Containment: No			
Comment:			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Barricade fencing for valve can.		

Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Stock panel and guard fencing.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Stock panel fencing around PBV, meter run, separators and telemetry equipment.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Dismantled at the time of this inspection.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.208029,-107.545547	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

Inspected Facilities									
Facility ID:	<u>216383</u>	Type:	<u>WELL</u>	API Number:	<u>067-07989</u>	Status:	<u>PA</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>269119</u>	Type:	<u>WELL</u>	API Number:	<u>067-08858</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>443350</u>	Type:	<u>WELL</u>	API Number:	<u>067-09955</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Ditches	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil container on secondary containment.
Waddles	Pass	Gravel	Pass			
Gravel	Pass					
Rip Rap	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On October 22, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Rhodes #1. For the most recent field inspection report of this facility, please refer to document #685200556.</p> <p>A workover rig temporarily abandoning the Rhodes #1 had recently left this location. A tubing trailer, air package, portable toilet, and horizontal tank remained on location at the time of this inspection.</p> <p>The pump jack, well head, and surrounding gravel were stained and wet.</p>	hughesjo	11/20/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800342	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4651687