

Inspection Photos
Location Name: Airco #2 Natural Gas Well
Spill/Release Point ID #458267



2,500 gallon fiberglass produced water AST where release occurred.



White residue present within secondary containment berm.

Inspection Photos
Location Name: Airco #2 Natural Gas Well
Spill/Release Point ID #458267



Impacted material was being removed from the location.



Impacted area on location had been scraped.

Inspection Photos
Location Name: Airco #2 Natural Gas Well
Spill/Release Point ID #458267



Looking upstream at the drainage feature that the release followed.



Pin flags in drainage feature along flow path.

Inspection Photos
Location Name: Airco #2 Natural Gas Well
Spill/Release Point ID #458267



Looking downstream within flow path.



Flow path leads to cliff edge.

Inspection Photos
Location Name: Airco #2 Natural Gas Well
Spill/Release Point ID #458267



Produced water flow path off of sandstone cliff.



Drainage feature that flow path terminated in.