

Inspection Photos

11/19/2018

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 327573

Inspection Doc. Number: 682504199
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the access road, facing north. Unable to find evidence that compaction alleviation has been conducted in accordance with 1004.a on access road.




Photo 2: Photo taken from the access road. Photo shows inspector tested the access road for compaction. Photo shows inspector was able to find a compaction layer only a couple of inches sub-surface. Unable to find evidence that compaction alleviation has been conducted in accordance with 1004.a on access road.



Photo 3: Photo taken from the south end of the location, facing northwest. Photos 3-5 provide an overview of the location from northwest, north, to northeast. Photos show reclamation does not appear to have been conducted in accordance with 1000 series reclamation requirements; 1004.a requires compaction alleviation to be conducted by cross-ripping to a depth of 18 inches. Location has not been cross ripped. Compaction concerns remain evident.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327573



Photo 4: See comments under photo 3.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 327573



Photo 5: See comments under photo 3



Photo 6: Photo taken from the location, facing south. Photo shows access road. See comments under photo 1.



Photo 7: Photo taken from the location, facing north. Photo shows inspector tested the location for compaction. Photo shows inspector was only able to penetrate the top couple of inches of soil on the areas of location that were not ripped. Compaction concerns evident.