

# Inspection Photos

11/19/2018

Operator: FOUNDATION ENERGY  
MANAGEMENT LLC - 10112

Location ID: 327445

Inspection Doc. Number: 682504201  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the access road, facing east. Unable to find evidence that compaction alleviation has been conducted in accordance with 1004.a on access road; access road does not appear to have been cross-ripped.



**Photo 2:** Photo taken from the access road, facing east. Photo shows inspector tested the location for compaction. Photo shows inspector found compaction zones a few inches sub-surface within areas of the road that were not cross-ripped.



**Photo 3:** See comments under photo 2.



**Photo 4:** See comments under photo 2.



**Photo 5:** Photo taken from the location, facing east. Photo shows overview of the location. Photo shows reclamation does not appear to have been conducted in accordance with 1000 series reclamation requirements; 1004.a requires compaction alleviation to be conducted by cross-ripping to a depth of 18 inches. Location has not been cross ripped. Compaction concerns remain evident.



**Photo 6:** Photo taken from the location. Photo shows inspector tested the location for compaction. Photo shows inspector was only able to penetrate the top couple of inches of soil on the areas of location that were not ripped. Compaction concerns evident.



**Photo 7:** See comments under photo 6.