

Construction and Stormwater Inspection

November 20, 2018

Operator: HIGHPOINT OPERATING CORPORATION- #10071

Location ID: 458768

Inspection Document #: 682404223

Weld County, CO

NWSW Section 4 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Wetco /4-63-4 SW
Location ID: 458768



Photo 1. Photo taken from the northern location, facing South. Photo illustrates the start of topsoil salvage operations.

Inspection Photos
Location Name: Wetco /4-63-4 SW
Location ID: 458768



Photo 2. Photo taken from the northern perimeter of the location, facing East. Photo illustrates a temporary stormwater BMP which has been installed around the entire perimeter of the location. Filtrex wattle has been staked and trenched.

Inspection Photos
Location Name: Wetco /4-63-4 SW
Location ID: 458768



Photo 3. Photo taken from the initial topsoil salvage area, facing East. COGCC Staff is observing that all topsoil is being salvaged. Operator stated that topsoil would be salvaged from the entire disturbance area to a depth of 12”.

Inspection Photos

Location Name: Wetco /4-63-4 SW

Location ID: 458768



Photo 4. Close-up photo illustrating the first subsoil layer (sand) being encountered at a depth of 12”.