

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/26/2018

Submitted Date:

11/21/2018

Document Number:

688800353**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
313551 _____ Hughes, Jim _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 1375Name of Operator: LINDE INCAddress: 200 SOMERSET CORP BLVD #7000City: BRIDGEWATER State: NJ Zip: 07083**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|---------------------------|---------------------------------------|
| Pecor, John | 970-385-1356 | jpecor@blm.gov | |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Fischer, Alex | | alex.fischer@state.co.us | |
| Hughes, Jerrod | 970-565-7021 | jerrod.hughes@linde.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 112976 | PIT | AC | | | - | AIRCO DUDLEY 5 | EI |
| 224457 | WELL | PR | 11/30/2007 | GW | 083-06522 | AIRCO DUDLEY 5 | EI |

General Comment:

On October 26, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Linde Inc. Airco Dudley #5. For the most recent field inspection report of this facility, please refer to document #685301848.

| Location | | | |
|--|---|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Free standing sign near well head. | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | Plant phone number listed on location sign. Linde representative answered call and stated that phone number is not manned 24/7. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | | Date: 12/21/2018 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Steel pipe barricade fence around well head. | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Dehydrator | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Flow Line | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 112976 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 224457 Type: WELL API Number: 083-06522 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | | | | | |
| Ditches | Pass | | | | | |
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: 112976 Lat: 37.376428 Long: -108.788487

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Plastic Liner Condition: Adequate

Comment: Leak detection system between liners.

Corrective Action

Date: _____

Fencing:

Fencing Type: Netting/Fence com Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: Fence/Net Combo Netting Condition: Good

Comment:

Corrective Action

Date: _____

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| On October 26, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Linde Inc. Airco Dudley #5. For the most recent field inspection report of this facility, please refer to document #685301848. The location sign is missing emergency contact information and a 24 contact number for the operator. | hughesjo | 11/21/2018 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 688800354 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4653551 |