

Inspection Photos
Location Name: Mark 11,12,14-35
Facility ID: 326785



Photo 1 – Location sign and removed flow lines behind livestock fencing.



Photo 2 – Additional removed flow lines outside of fenced area.

Inspection Photos
Location Name: Mark 11,12,14-35
Facility ID: 326785



Photo 3 – Western pit; remedial vacuuming of groundwater had ended approximately 15 minutes prior to picture.



Photo 4 – Groundwater recharging into western pit.

Inspection Photos
Location Name: Mark 11,12,14-35
Facility ID: 326785



Photo 5 – Recharging groundwater carrying impacted sediment into excavation area along the southeastern wall.

Inspection Photos
Location Name: Mark 11,12,14-35
Facility ID: 326785



Photo 6 – Recharging groundwater carrying impacted sediment into excavation area along the southeastern wall.



Photo 7 – Groundwater flowing into north wall. No signs of impact in deposited sediment

Inspection Photos
Location Name: Mark 11,12,14-35
Facility ID: 326785



Photo 8 – Stabilized groundwater in eastern pit.



Photo 9 – Flow lines in place on sidewall of eastern pit.

Inspection Photos
Location Name: Mark 11,12,14-35
Facility ID: 326785



Latitude: 40.365735
Longitude: -104.706342
Time: 11-21-2018 12:00

Photo 10 – Site overview; Eastern pit in foreground.

Inspection Photos
Location Name: Mark 11,12,14-35
Facility ID: 326785



Photo 11 – Adjacent irrigation canal. Flowing at time of inspection.



Latitude: 40.26477
Longitude: -104.635309
Time: 11-21-2018 12:03
COGCC

Photo 12 – Photo of site from adjacent irrigation canal.