

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/27/2018

Submitted Date:

11/27/2018

Document Number:

689302441**FIELD INSPECTION FORM**

Loc ID 335079 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**20 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sgghan@vnrenergy.com	SR. EH&S

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
54	WELL	PR	04/17/2008	GW	045-15433	SCOTT 34A-25-692	AC
275249	WELL	SI	09/01/2018	GW	045-13498	SCOTT 24B-25-692	AC
275250	WELL	PR	07/28/2005	GW	045-13499	SCOTT 34C-25-692	AC
275864	WELL	PR	07/27/2005	GW	045-10393	SCOTT 24D-25-692	PR
275866	WELL	PR	04/06/2008	GW	045-10391	SCOTT 24C-25-692	AC
292244	WELL	PR	04/17/2008	GW	045-14653	SCOTT 34B-25-692	AC
292245	WELL	PR	04/14/2008	GW	045-14652	SCOTT 34D-25-692	AC
292246	WELL	PR	04/25/2008	GW	045-14651	SCOTT 33A-25-692	AC
292247	WELL	PR	03/03/2016	GW	045-14650	SCOTT 24A-25-692	AC

**General Comment:**

Routine Field Inspection.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-921-8252

Corrective Action:

Date:

**Good Housekeeping:**

Type	WEEDS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Horizontal Heated Separator	# 9			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 3			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heater Treater	# 1			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 9			
Comment:				
Corrective Action:				Date:
Type: Pig Station	# 1			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 9			
Comment:	8 active injection meters			
Corrective Action:				Date:
Type: Bird Protectors	# 10			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLs	HEATED STEEL AST		,	
Comment:	4 tanks in a centralized battery.					
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	YES					
Comment:	Bradenhead valves open to vent.					
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	54	Type:	WELL	API Number:	045-15433	Status:	PR	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift. Active injection.								
Corrective Action:						Date:			
Facility ID:	275249	Type:	WELL	API Number:	045-13498	Status:	SI	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift. Active injection.								
Corrective Action:						Date:			
Facility ID:	275250	Type:	WELL	API Number:	045-13499	Status:	PR	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift. Active injection.								
Corrective Action:						Date:			
Facility ID:	275864	Type:	WELL	API Number:	045-10393	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	275866	Type:	WELL	API Number:	045-10391	Status:	PR	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift. Active injection.								
Corrective Action:						Date:			
Facility ID:	292244	Type:	WELL	API Number:	045-14653	Status:	PR	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift. Active injection.								
Corrective Action:						Date:			
Facility ID:	292245	Type:	WELL	API Number:	045-14652	Status:	PR	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift. Active injection.								
Corrective Action:						Date:			
Facility ID:	292246	Type:	WELL	API Number:	045-14651	Status:	PR	Insp. Status:	AC

<b>Producing Well</b>			
Comment:	Well Producing on plunger lift. Active injection.		
Corrective Action:		Date:	

Facility ID:	292247	Type:	WELL	API Number:	045-14650	Status:	PR	Insp. Status:	AC
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<b>Producing Well</b>			
Comment:	Well Producing on plunger lift. Active injection.		
Corrective Action:		Date:	

--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Gravel				
Berms						
Rip Rap						
		Compaction				
Ditches						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302442	Inspection photo 689302442	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4656786">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4656786</a>