

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/27/2018

Submitted Date:

11/27/2018

Document Number:

689302445

FIELD INSPECTION FORM

Loc ID 417475 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 16 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417404	WELL	PR	08/02/2011	GW	045-19508	MILLER 14C-31-691	PR
417412	WELL	PR	08/15/2011	GW	045-19513	MILLER 14A-31-691	PR
417422	WELL	PR	08/15/2011	GW	045-19520	GGU Miller 13A-31-691	PR
417447	WELL	PR	08/02/2011	GW	045-19530	GGU LINKENHOKER 23A-31-691	PR
417450	WELL	PR	05/25/2010	GW	045-19531	MILLER 14D-31-691	PR
417471	WELL	PR	08/02/2011	GW	045-19544	MILLER 14B-31-691	PR

General Comment:

[Routine Field Inspection.](#)
[Location is snowed covered.](#)

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:

Overall Good:

Emergency Contact Number:			
Comment:	1-800-921-8252		
Corrective Action:			Date:

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	WEEDS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panel fence.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 1		
Comment:	chemical unit at wellhead.		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	500 BBLs	HEATED STEEL AST		,
Comment:	8 tanks in a centralized battery.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES	
Comment:	Bradenhead valves open to vent.	
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	417404	Type:	WELL	API Number:	045-19508	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	417412	Type:	WELL	API Number:	045-19513	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	417422	Type:	WELL	API Number:	045-19520	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	417447	Type:	WELL	API Number:	045-19530	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	417450	Type:	WELL	API Number:	045-19531	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	417471	Type:	WELL	API Number:	045-19544	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Ditches						
		Gravel				
Berms						
Retention Ponds						
Rip Rap						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302446	Inspection photo 689302446	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4656788