

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/27/2018

Submitted Date:

11/28/2018

Document Number:

691200852

FIELD INSPECTION FORM

Loc ID 317523 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96155
Name of Operator: WHITING OIL & GAS CORPORATION
Address: 1700 BROADWAY STE 2300
City: DENVER State: CO Zip: 80290

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		WhitingEasternCO@Whiting.com	Eastern Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238910	WELL	SI	06/01/2014	OW	123-05787	NELSON RANCHES 1	TA

General Comment:

This is a WELL Inspection.
Follow-up to FIR #691200450 dated 09/12/2018.
3 of 3 Corrective Action items have been addressed
Did not inspect decommissioned battery site.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Barbed wire		
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked	# 4		corrective date
Comment:	4 /4-marked		
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:	Stained soil underneath wellhead piping appears to be remediated. This addresses the CA item from FIR #691200450 dated 09/12/2018. Plunger lift & piping have been removed. Well has master valve only.		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:	The venting 2" union connection was removed. Well is securely SI. Was verbally notified on telephone by Whiting foreman on 09/14/2018 that the leak/venting was stopped and site remediated. This addresses the CA item from FIR #691200450 dated 09/12/2018.		
Corrective Action:			Date:
Flaring:			
Type			

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 238910 Type: WELL API Number: 123-05787 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Well appears to be in TA status. Wellhead has master valve only. Disconnected from flowline. Not capable of producing in current status. Records indicate last production was 05/2014. Form 21 #401762376 indicates a MIT was performed on 10/18/2018. Final approval still in process.

Corrective Action:

Date:

BradenHead

Comment: Bradenhead does appear plumbed to surface.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200853	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4657719