

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/27/2018

Submitted Date:

11/28/2018

Document Number:

691200854**FIELD INSPECTION FORM**Loc ID 317522 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 BROADWAY STE 2300City: DENVER State: CO Zip: 80290**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		WhitingEasternCO@Whiting.com	Eastern Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238909	WELL	SI	09/01/2014	GW	123-05786	NELSON RANCHES 4	TA

General Comment:

This is a WELL Inspection.
Follow-up to FIR #691200447 dated 09/12/2018.
3 of 3 Corrective Action items have been addressed
Did not inspect decommissioned battery site.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds have been cleared from wellsite. This addresses the CA item from FIR #691200447 dated 09/12/2018.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	4/4-marked		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead w/ ball valve on tubing. Pulled rods are stacked on pallets.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 238909 Type: WELL API Number: 123-05786 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Well appears to be in TA status. Wellhead has master valve only. Disconnected from flowline. Not capable of producing in current status.
Records indicate last production was 08/2014.
Form 21 #401762402 indicates a MIT was done on 10/31/2018. MIT was approved by COGCC Engineering on 11/26/2018.
This addresses the CA item from FIR #691200447 dated 09/12/2018.

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead does NOT appear plumbed to surface.
FIRR indicates bradenhead was cemented by previous operator.
Whiting has contacted COGCC Engineering for direction.
This addresses the CA item from FIR #691200447 dated 09/12/2018.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200855	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4657720