

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2018

Submitted Date:

11/29/2018

Document Number:

689302477**FIELD INSPECTION FORM**
 Loc ID 335501 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298784	WELL	PR	04/05/2010	GW	045-17417	DOMMER 33D-26-692	PR
298785	WELL	PR	05/17/2010	GW	045-17418	DOMMER 33B-26-692	PR
298787	WELL	PR	05/17/2010	GW	045-17419	DOMMER 23A-26-692	PR
298788	WELL	PR	04/05/2010	GW	045-17420	DOMMER 23D-26-692	PR
298789	WELL	PR	05/17/2010	GW	045-17421	DOMMER 32A-26-692	PR
298790	WELL	PR	05/17/2010	GW	045-17422	DOMMER 33A-26-692	PR
298791	WELL	PR	04/05/2010	GW	045-17423	DOMMER 22A-26-692	PR
298792	WELL	PR	05/12/2010	GW	045-17424	DOMMER 33C-26-692	PR
298793	WELL	PR	05/12/2010	GW	045-17425	DOMMER 23B-26-692	PR

General Comment:

This is a follow up inspection from Doc# 689302163. Required Corrective Action (s) items noted in previous inspections have been satisfied. Location is snow covered at the time of re-inspection.
Equipment inventory has not changed on location.

Inspected Facilities									
Facility ID:	298784	Type:	WELL	API Number:	045-17417	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	298785	Type:	WELL	API Number:	045-17418	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	298787	Type:	WELL	API Number:	045-17419	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	298788	Type:	WELL	API Number:	045-17420	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	298789	Type:	WELL	API Number:	045-17421	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	298790	Type:	WELL	API Number:	045-17422	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	298791	Type:	WELL	API Number:	045-17423	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	298792	Type:	WELL	API Number:	045-17424	Status:	PR	Insp. Status:	PR

Producing WellComment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 298793 Type: WELL API Number: 045-17425 Status: PR Insp. Status: PR**Producing Well**Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302478	Inspection photo 689302478	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4659582