

Inspection Photos
Operator Name: TEP Rocky Mountain
Location ID: 429828



Poly Flowline



Poly Flowline cut into 30' joints

Inspection Photos
Operator Name: TEP Rocky Mountain
Location ID: 429828



Steel Flowlines



Steel flowlines

Inspection Photos
Operator Name: TEP Rocky Mountain
Location ID: 429828



Poly flowline from pit towards location



Poly and steel flowline from pit towards location

Inspection Photos
Operator Name: TEP Rocky Mountain
Location ID: 429828



Pit and cement drainage structure



Pit Inlet flowline

Inspection Photos
Operator Name: TEP Rocky Mountain
Location ID: 429828



Poly exiting pit