

Inspection Photos

Operator: Petrox Resources

API: 05-007-06278

Date: 11/06/2018



Photo 1. View of the project area from northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing within portions of the interim reclamation with grasses such as western wheatgrass (*Pascopyrum smithii*) area and sparse in other portions.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of the southeastern project area.