

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/07/2018

Submitted Date:

11/30/2018

Document Number:

688800369**FIELD INSPECTION FORM**

Loc ID 335658 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10091
 Name of Operator: BERRY PETROLEUM COMPANY LLC
 Address: 5201 TRUXTUN AVENUE #100
 City: BAKERSFIELD State: CA Zip: 90339

Findings:

- 8 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|---------------------------|--------------------------------------|
| Johnson, Derek | 970-285-2200 | djohnson@bry.com | Dist. Superintendent |
| Fischer, Alex | | alex.fischer@state.co.us | |
| Wilbourn, Don | | dwilbourn@bry.com | |
| Arauzo, Steven | | steven.arauza@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|-----------------------|--------|-------------|------------|---------|------------------|-------------|
| 443325 | LAND APPLICATION SITE | AC | 09/25/2015 | | - | Chevron 036B 596 | EI |

General Comment:

On November 7, 2018 COGCC Western Environmental Supervisor Alex Fischer, and EPS staff members Stan Spencer, Steven Arauzo, and Jim Hughes conducted an environmental field inspection of the Berry Chevron O36B 596 Land Application Site, Facility ID #443325. For the most recent field inspection report of this facility, please refer to document #688800199. Berry representatives Derek Johnson and Don Wilbourn were on site during this inspection.

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |

Overall Good:

| | | | |
|----------------------|--|--|-------|
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Free standing sign near location entrance. | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|--------------------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | Posted on location sign. | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|---|--|------------------|
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Joints of unused steel pipe stored in secondary containment berm. | | |
| Corrective Action: | Comply with Rule 603.f. | | Date: 12/31/2018 |
| Type | DEBRIS | | |
| Comment: | Continue to remove liner pieces as they become exposed. | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|--|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |

| | | | |
|--------------------|--|--|-------|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|--|--|-------|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 443325 Type: LAND API Number: - Status: AC Insp. Status: EI

Environmental

Waste Management:

| Type | Management | Condition | GPS (Lat) (Long) | |
|-------------------|---|-----------|------------------|--|
| Drill Cuttings | Land Treatment | Adequate | | |
| Comment | Please refer to REM #10236 for more information regarding this remediation project. | | | |
| Corrective Action | | | Date: | |

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | | | Material Handling And Spill Prevention | Pass | |
| | | | | Self Inspection | Pass | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>On November 7, 2018 COGCC Western Environmental Supervisor Alex Fischer, and EPS staff members Stan Spencer, Steven Arauza, and Jim Hughes conducted an environmental field inspection of the Berry Chevron O36B 596 Land Application Site, Facility ID #443325. For the most recent field inspection report of this facility, please refer to document #688800199. Berry representatives Derek Johnson and Don Wilbourn were on site during this inspection.</p> <p>Compliant material has been moved from the eastern portion of the location to the pit area, to allow for spreading of more material from the western edge of the location.</p> <p>Continue to remove liner pieces from land farm as they become exposed.</p> <p>Steel pipe joints observed in secondary containment berm during this inspection. If these are not necessary for operations at this location, they need to be removed.</p> | hughesjo | 11/30/2018 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 688800370 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4660947 |