

Inspection Photos

Operator: Petrox Resources

API: 05-007-06269

Date: 11/06/2018



Photo 1. View of the project area from southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Outer portions of the project area are bermed and trees are planted. Understory is largely weeds such as cheatgrass (*Bromus tectorum*) and Russian thistle (*Salsola tragus*).



Photo 3. View of the southern project area from the southwestern corner facing eastward.

Spotted knapweed

Musk thistle



Photo 4. View of noxious weeds: spotted knapweed (*Centaurea maculosa*) and musk thistle (*Carduus nutans*) growing on the outer project berms within the project area.. Approximately 200 spotted knapweed and 150 musk thistles observed.



Photo 5. View of the western project berm that needs to be stabilized with perennial vegetation or otherwise stabilized.