

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2018

Submitted Date:

11/30/2018

Document Number:

689302487**FIELD INSPECTION FORM**
 Loc ID 334865 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☒ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211250	WELL	PR	05/28/2004	GW	045-07009	COUEY 18-10	PR
266473	WELL	PR	05/28/2004	GW	045-09148	PITMAN 18-7D(J18)	PR
268474	WELL	PR	08/01/2018	GW	045-09262	HMU 18-10D(J18)	PR
268984	WELL	PR	08/01/2013	GW	045-09263	HMU 18-10C(J18)	PR

General Comment:[Any corrective actions from previous inspections that have not been addressed are still applicable.](#)[This is a follow up inspection from Doc# 689302192. CA's as specified as required were not met.
Equipment inventory has not changed on location.](#)[Location is snow covered.](#)

Inspected Facilities									
Facility ID:	211250	Type:	WELL	API Number:	045-07009	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	266473	Type:	WELL	API Number:	045-09148	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	268474	Type:	WELL	API Number:	045-09262	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	268984	Type:	WELL	API Number:	045-09263	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Sediment being moved off location on the South side of location.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 11/25/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302488	Inspection photo 689302488	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4661010