

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2018

Submitted Date:

11/30/2018

Document Number:

689302483**FIELD INSPECTION FORM**

Loc ID 335511 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300395	WELL	PR	06/01/2011	GW	045-17901	DOWNING RWF 522-24	PR
300396	WELL	PR	06/30/2010	GW	045-17902	DOWNING RWF 22-24	PR
300397	WELL	PR	06/30/2010	GW	045-17903	DOWNING RWF 511-24	PR
300398	WELL	PR	06/30/2010	GW	045-17904	DOWNING RWF 311-24	PR

General Comment:

This is a follow up inspection from Doc# 689302114. Required Corrective Action (s) items noted in previous inspections have been satisfied.
 Equipment inventory has not changed on location.
 Location is snow covered.

Inspected FacilitiesFacility ID: 300395 Type: WELL API Number: 045-17901 Status: PR Insp. Status: PR**Producing Well**Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 300396 Type: WELL API Number: 045-17902 Status: PR Insp. Status: PR**Producing Well**Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 300397 Type: WELL API Number: 045-17903 Status: PR Insp. Status: PR**Producing Well**Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 300398 Type: WELL API Number: 045-17904 Status: PR Insp. Status: PR**Producing Well**Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302484	Inspection photo 689302484	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4661008