

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2018

Submitted Date:

11/30/2018

Document Number:

688800373**FIELD INSPECTION FORM**
 Loc ID 335876 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 5201 TRUXTUN AVENUE #100City: BAKERSFIELD State: CA Zip: 90339**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Johnson, Derek	970-285-2200	djohnson@bry.com	<a href="#">Dist. Superintendent</a>
Wilbourn, Don		dwilbourn@bry.com	
Fischer, Alex		alex.fischer@state.co.us	
Arauza, Steven		steven.arauza@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449190	LAND APPLICATION SITE	AC	02/10/2017		-	C10 696 449190	EI

**General Comment:**

On November 8, 2018 COGCC West Environmental Supervisor Alex Fischer, EPS staff members Steven Arauza and Jim Hughes, and Reclamation Specialist Lou Colby conducted an environmental field inspection of the Berry C10 696. For the most recent field inspection report of this facility, please refer to document #688800146.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Continue to remove liner pieces as they become exposed in land farmed material.		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	449190	Type:	LAND	API Number:	-	Status:	AC	Insp. Status:	EI

--

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Drill Cuttings	Land Treatment	Adequate		
Comment	Please refer to REM #10240 in the COGIS database for more information regarding this project.			
Corrective Action				Date:

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): Comment: Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Self Inspection	Pass	
				Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Drilling PitLined: ☐Pit ID: 450300Lat: 39.543698Long: -108.095506Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: 

Liner has been removed. Pit will be backfilled with land farmed material on site upon completion of REM #10240.

Corrective Action Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action Date: Anchor Trench Present: ☐Oil Accumulation: ☐2+ feet Freeboard: ☐Comment: Corrective Action Date: **COGCC Comments**

Comment	User	Date
On November 8, 2018 COGCC West Environmental Supervisor Alex Fischer, EPS staff members Steven Arauza and Jim Hughes, and Reclamation Specialist Lou Colby conducted an environmental field inspection of the Berry C10 696. For the most recent field inspection report of this facility, please refer to document #688800146. Berry representatives Derek Johnson and Don Wilbourn were on site during this inspection. Options were discussed for redistributing the land farmed material more evenly. Presently the cuttings require a track hoe to turn because of the thickness of the material. Continue to remove liner pieces as they become exposed in the land farmed material.	hughesjo	11/30/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800374	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4661184">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4661184</a>