

Inspection Photos

Operator: Petrox Resources

API: 05-007-06272

Date: 11/06/2018



Photo 1. View of the project area from southwestern edge facing center.



Photo 2. View of the northwestern project area from the western edge facing northward. Irrigation ditch runs adjacent to this area. Stormwater runoff needs to be carefully monitored to prevent contamination of waterway due to proximity. Tires, culvert, and other debris need to be removed.



Photo 3. View of the southern project area from the southeastern corner facing center. Little desirable vegetation growing hear. Area appears to need seeding/revegetation.



Photo 4. View of the eastern project area from the southeastern corner facing northward.



Photo 5. View of Canada thistles (*Cirsium arvense*) within the eastern project area.